Project Number:	ici icepiace	ment						
	C2	001						
Project Status:			1	Existing	1	Amended		
Affiliated Bond Account(s):	HKV3	-		_		_		
Amendment(s):								
2022-2026	increase co	st.						
2023-2027	updatd fun	ding needs.						
Events are getting bigger and their expectation		-		-	-		-	•
need to bring in a generator. This may ma		-	-					-
in our switchgear, but work is needed to e		make it ava	lable. The	ere are also s	several tran	isformers that	t are over 2	20 years
old and should be replaced before they fai					• • • •			- 1
	Pre 2023	2023	2024	2025	2026	2027	2028	Total
County	0.100	0.300						0.400
Other	0.100	0.000						-
Total County Cost	0.100	0.300	-	-	-	-	-	0.400
Low Roof Replacement								
Project Number:	C2(002						
Project Status:		New	1	Existing		Amended		
Affiliated Bond Account(s):	HKV3	-		_		-		
Amendment(s):								
The low roof is the last of the roofs that no	eed replace	nent. There	have been	several leak	s over rend	ovated areas t	hat need pa	atching.
The leaks seem to be coming from age, se	als coming	loose and ge	eneral wea	r and tear.				
Year	Pre 2023	2023	2024	2025	2026	2027	2028	Total
County	0.308							0.308
Other								-
Total County Cost	0.308							
Total County Cost	0.500	-	-	-	-	-	-	0.308
		-	-	-	-	-	-	0.308
Stairwell Enclosure Concourse Floor	ring	-	-	-	-	-	-	0.308
Stairwell Enclosure Concourse Floor Project Number:	ring C2		-	-	-	-	-	0.308
Stairwell Enclosure Concourse Floor Project Number: Project Status:	ring C2	201 New	-	Existing	-	Amended	-	0.308
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s):	ring C2		-	Existing		Amended	-	0.308
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s):	ring C2	New			-	Amended	-	0.308
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027	'ing C2 Incrporatin	New	e and Floo	ring project.		_	-	
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren	ing C2 Incrporatin a has been u	New g Concourse unsightly due	e and Floo e to being	ring project. unable to ke	ep wildlife	out. There h		nultiple
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success	ing C2 Incrporatin a has been u s. Enclosing	New g Concourse insightly due these stairw	e and Floo e to being vells will a	ring project. unable to ke	ep wildlife ep animals	out. There h	also provid	nultiple e an extra
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the	ing C2 Incrporatin a has been u s. Enclosing adjacent are	New g Concourse unsightly due these stairwea. There are	e and Floo e to being vells will a e multiple	ring project. unable to ke llow us to ke railings that	ep wildlife ep animals are determ	out. There h s out. It will a ined due to st	also provide reet salt an	nultiple e an extra id weather
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps	ing C2 Incrporatin a has been u s. Enclosing adjacent are / facades th	New g Concourse unsightly due these stairwe a. There are at need reco	e and Floo e to being yells will a multiple ntruction o	ring project. unable to ke llow us to ke railings that or replacing a	ep wildlife ep animals are determ around the	out. There h s out. It will a ined due to st entire proper	llso provide reet salt an ty. The cou	nultiple e an extra id weather ncourse
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou	Ting C2 Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize	New g Concourse insightly due these stairwe a. There are at need reco id as a reven	e and Floo e to being yells will a multiple in ntruction of ue generat	ring project. unable to ke llow us to ke railings that a or replacing a ting event sp	ep wildlife eep animals are determ around the ace. We ar	out. There h s out. It will a ined due to st entire proper e looking to a	llso provide creet salt an ty. The con add a coole	nultiple e an extra id weather ncourse er to the
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou concourse level for concessions to restock	ing C2: Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize the stands	New g Concourse insightly due these stairwe a. There are at need reco id as a reven quicker. The	e and Floo e to being vells will a e multiple ntruction o ue generat e stairs goi	ring project. unable to kee llow us to kee railings that or replacing a ting event sp ing from the	ep wildlife eep animals are determ around the ace. We ar concourse	out. There h s out. It will a ined due to st entire proper e looking to a level to the b	Ilso provident reet salt an ty. The contradd a coole add a coole	nultiple e an extra id weather ncourse er to the bbies are
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou concourse level for concessions to restock the only flooring area that has not been rest	ing C2: Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize the stands	New g Concourse insightly due these stairwe a. There are at need reco id as a reven quicker. The	e and Floo e to being vells will a e multiple ntruction o ue generat e stairs goi	ring project. unable to kee llow us to kee railings that or replacing a ting event sp ing from the	ep wildlife eep animals are determ around the ace. We ar concourse	out. There h s out. It will a ined due to st entire proper e looking to a level to the b	Ilso provident reet salt an ty. The contradd a coole add a coole	nultiple e an extra id weather ncourse er to the bbies are
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Amendment(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou concourse level for concessions to restock the only flooring area that has not been restincluded in this project.	Ting C2 Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize the stands finished and	New g Concourse insightly due these stairwe at need reco at need reco d as a reven quicker. The l we are look	e and Floo e to being vells will a multiple ntruction of ue generat e stairs goi king to hav	ring project. unable to kee llow us to kee railings that or replacing a ting event sp ing from the ve completed	ep wildlife eep animals are determ around the ace. We ar concourse . Refinishi	out. There h s out. It will a ined due to st entire proper e looking to a level to the b ng the kitche	Ilso provide reet salt an ty. The con add a coole athroom lo n floor will	nultiple e an extra d weather ncourse er to the bbies are also be
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Affiliated Bond Account(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou concourse level for concessions to restock the only flooring area that has not been rei included in this project.	ing C2: Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize the stands	New g Concourse insightly due these stairwe a. There are at need reco id as a reven quicker. The	e and Floo e to being vells will a e multiple ntruction o ue generat e stairs goi	ring project. unable to kee llow us to kee railings that or replacing a ting event sp ing from the	ep wildlife eep animals are determ around the ace. We ar concourse	out. There h s out. It will a ined due to st entire proper e looking to a level to the b	Ilso provident reet salt an ty. The contradd a coole add a coole	e an extra ad weather ncourse er to the bbies are
Stairwell Enclosure Concourse Floor Project Number: Project Status: Affiliated Bond Account(s): Affiliated Bond Account(s): 2023-2027 The stairwells on the East side of the aren attempts by several means with no success level of security and utility savings to the damage. There are various concrete steps entrance from the MVP Arena garage cou concourse level for concessions to restock the only flooring area that has not been restincluded in this project.	Ting C2 Incrporatin a has been u s. Enclosing adjacent are / facades th ld be utilize the stands finished and	New g Concourse insightly due these stairwe at need reco id as a reven quicker. The l we are look 2023	e and Floo e to being vells will a e multiple ntruction o ue generat e stairs goi king to hav 2024	ring project. unable to kee llow us to kee railings that or replacing a ting event sp ing from the ve completed	ep wildlife eep animals are determ around the ace. We ar concourse . Refinishi	out. There h s out. It will a ined due to st entire proper e looking to a level to the b ng the kitche	Ilso provide reet salt an ty. The con add a coole athroom lo n floor will	nultiple e an extra id weather ncourse er to the bbies are also be Total