Arena Equipment Replacement

Project Number: Debt Account: HKUY

All equipment is at least 15 years old. Replace staging that is old and degrading. Spotlights are in need of frequent repair and replacement parts. Existing barricade lacks step to assist patrons from GA floor. The Project Description: turnstiles are needed for accurate counts of patrons entering. Forklifts are up in age. The West End curtains

will cover the lights in the suites for end stage shows that production often have concerns about during

shows.

Amendment(s):

Project Status:New	1	Existing		Amended		Continual		Completed
Authorized Funding	Pre-2024	2024	2025	2026	2027	2028	2029	Total
County	0.597							0.597
State								
Federal								
Other								-
Total Project Cost	0.597	-	-	-	-	-	-	0.597

Replacement of Chiller, BMS Control, Concourse heat/Fan Coil Replacement, Lighting Upgrade

Project Number: C1902 **Debt Account: HKUZ**

> Comfort Chiller is original to building construction and is past its useful life. The work for this project would also include replacement of motors, pumps, valves and suction diffusers. This work will offer significant energy reduction savings. This project is needed to run the building more efficiently and help accommodate

Project Description: the increased building load of the front atrium enclosure. Building sealing is needed to prevent loss of conditioned air. Concourse heat is needed rather than ambient from arena bowl. Additional BMS controls to automate more systems for energy conservation. Lighting upgrades are to replace high energy consumption bulbs.

Amendment(s):

Project Status:New	1	Existing		Amended		Continual		Completed
Authorized Funding	Pre-2024	2024	2025	2026	2027	2028	2029	Total
County	1.950			-	-	-	-	1.950
State								
Federal								
Other								-
Total Project Cost	1.950	-	-	-	-	-	-	1.950

Arena Floor, Kitchen Floor, Quad Stairs Refinishing and Atrium door patching

Project Number: C1903 **Debt Account:**

The main arena floor has sustained several significant gouges. Rebar is showing in several areas. There have been several attempts to patch, but they continue to come out. The kitchen floor has had years of wear and Project Description: tear. The existing floor covering is coming up in pieces and makes the kitchen look unsanitary. The Quad stairs going to the bathrooms stick out because it sits next to the refinished concourse and bathroom lobby

floors.

Amendment(s):

Project Status: New	1	Existing		Amended		Continual		Completed
Authorized Funding	Pre-2024	2024	2025	2026	2027	2028	2029	Total
County	0.500							0.500
State								
Federal								
Other								-
Total Project Cost	0.500	-	-	-	-	-	-	0.500